Trinity Contracting, LLC 321-591-7168 **General Information** Job: xxxx Jean St **Building Description** Attribute Description / Type Address / Comments Age (approximate) 1986 XXXXXXXXXXXXXXXXXXXXXXXXXX 1320 + 604 Garage + porches Area (approximate) xxxx Jean St Building type Single Family Cocoa, FL Duplex / Twinplex Condominium Other - see comments Construction Frame Brick Block Other - see comments **Grounds** Comments Slope away from house X X Driveway Concrete Porch X Concrete X Patio / deck Concrete base, wood deck over concrete Deck Wood deck partially around pool X Additional comments: Panel is loose and bent on kickplate on rear porch next to screen door. Recommend reattach Hilities

Description	Source / type	Comments	
Water	x Public		
	Deep well		
	Point well		
	See comments		
0 / 5	Natural res		
Gas / Fuel	Natural gas		
	Propane		
	Fuel oil		
	See comments		
Caa.a.	Dublic		
Sewage	Public		
	x Septic tank and drain fill		
	See comments		

Weather at time of inspection

Temperature	Start Time a	ınd Date	General Conditions
62F	16:00	02/10/10	Sunny and clear

©2000-2005 Best Inspectors Network, MSI International, Inc.

all rights reserved

Roof Job: xxxx Jean St

Item / Attribute	Type / Style	Condition Comments
Roof (structure)	x Gable	X Good / Fair
	Hip Shed	Warped Damage
	See comments	Unstable / Needs immediate repair
	oee comments	Offstable / Needs infinediate repair
Roof covering	X Shingle	X Good / Fair 3 tab
_	Membrane/ built-up / Roll	Missing pcs.
	Slate, Tile	Damage
	See comments	Needs immediate repair
Danainia a lifa		David 40/0000
Remaining life Estimated	zero to five years X Greater than five years	Reroof 10/2002
LStimated	See comments	
		
Slope	x Low, medium	
	Steep	
	Flat	
	See comments	
Chimney	x WOOD	Good / Fair Chimney needs caulked and painted
Chilliney	Metal	X Minor wear
	Stone	Unstable Chimney cap loose and needs painted
	NA / See comments	Damaged, missing, or broken cap / screen
	Location/height acceptable	Location/heightNOT acceptable
Gutters,	x Metal	X Good / Fair Gutters are full of debris and do not
downspouts	Plastic	Inadequate drain properly. Recommend clean out and
	See comments	Damage seal joints and corners
		Missing pieces
Ventilation	x Static	X Good Ridge Vent
Ventuation	Powered	Fair
	NA / See comments	Marginal
	<u> </u>	Poor
Inspected from		
Item / Attribute		
		C V Visibility Comments
R = Roof		X X Good
C = Chimney V = Ventilators	Ground X X X Roof	Fair
v = ventilators	X X X Roof See comments	Marginal Poor
	Joe comments	
Additional comn	nents	

Note: red boxes indicating damage or items marked as needing immediate repair may result in further damage or may present a health or safety hazard if not repaired

Exterior and Attachments

Job: xxxx Jean St

General

	1 2 3			1 2 3	
x Covering	х	Stucco	x Foundation	х	Concrete
	х	Wood			Block
		Block			Brick
		Vinyl / metal siding			See comments
		Brick			
		-			_
x Windows,	х	Wood	x Fascia, trim,		Wood
Doors	х	Metal	Soffits	х	Metal
		Fiberglass			Vinyl
					See comments
		٦			_
x Water	х	Tested	x REPAIRS	х	Stucco
faucets		Not tested	NEEDED		Paint
		See comments			Siding
Comments					See comments
Stucco has large sett	lement crack or	n East side next to wind	ow. Recommend seal	crack, stucco	patch, and paint
Front door has wood	rot on lower 6 in	nches of both sides of c	loor jamb. Recommen	d replace botto	om of jambs
Fascia on east side g	able has large	dent and fold. Not sure	as to cause. Recomm	end remove a	nd inspect for truss damage
Rear french door is n	nissing bottom s	slide lock on stationary	door, doors will not lock	properly. Red	commend replace k

Garages, Sheds, Out buildings

Garages, Sileus	, Ou	יטייו	ши	iiigs						
x Garage / shed	1 x	2	3	Attached Detached Storage shed See comments		PAIRS EDED	1	2	3	O.H. Door Paint Siding See comments
x Overhead door	1 X	2	3	Metal Wood Fiberglass See comments	x Floo	or	1 X	2	3	Good Minor/settling cracks Deep cracks See comments
x Door opener	х			Tested Not tested	x Saf	ety eye	х			Tested Not tested / tested, Not working properly
x GFCI outlets*	1 x	2	3	Tested None / not working See comments	x O.H spri			Exte Note	nsioi :exte	(recommended) In (recommend replacing with torsion springs) Pension springs can present a saftety hazard if they Properly maintained
Comments Garage door is padlog	cked.	Canr	not te	est door, door opener,	or safetv e	ve at this tim	e	arer	ю р	торену таптатес
,				ag as designed. Becom						

GFCI plug and circuit is not functioning as designed. Recommend replace GFCI plug

Garage ceiling has several area of missing popcorn texture. No sign of water leak/damage. Common occurance due to humidity.
The absence of GFCI electrical outlets is not a deficiency or defect. However, GFCI outlets are recommended for all outdoor outlets grade level access, garages, al workshop areas

Interior living spaces and Attic

Item / Attribute	Type / Description	Condition	Comments
Floors	Linoleum Wood x Carpet x Tile	x Good Fair Uneven Damaged	
Walls / Celings	x Plaster, drywall Masonry Wood See comments	x Good Minor cracks Damaged Unstable	
Doors	x Interior doors	x Good Fair Marginal Poor	
Fireplace	masonry, brick Wood burner None Other / see comments	x Good / Fair Need to clean Cracks x Repair needs	Recommend replace screen

Job:

xxxx Jean St

Attic

Item / Attribute	Type / Style	Comments
Access	Closet Hall x Garage x See comments	Secondary scuttle front guest bedroom
Floor	Yes x Partial None	
Insulation	x Fiberglass Cellulose None See comments	Good x Fair Marginal Poor
Moisture	x None visible Damp, moist Fresh stains Old stains	x Good Fair Marginal Poor
Whole house Fan	See comments	Tested Not tested

Additional comments

Note: RED check boxes, when checked, indicate that attention is needed. Failure to attend to these items may result in damage or create a safety hazard.

Kitchen Job: xxxx Jean St

			1
	Δn	ıera	П
•	vii		Ш

Item / Attribute	Type / Description	Condition	Comments
Floor	Linoleum Wood Carpet x Tile	x Good Fair Uneven Damaged	
Electrical outlets in counter and sink areas	GFCI protected x Not GFCI See comments	Good x Fair Marginal Needs repa	air
Plumbing	X No leaks visible Leaks visible Corrosion See comments	X Good Fair Marginal Poor	
Counter tops	X Laminate Solid surface Marble/stone See comments	X Good Fair Marginal Poor	
Cabinets	x Wood Other Damaged See comments	x Good Fair Marginal Poor	
Comments			
	xes, when checked, indicate or create a safety hazard.	te that attention is	needed. Failure to attend to these items
Abscense of GFI elec	trical receptacles does not	constitute a defici	ency or defect. However,
GEL electrical recenta	icles are recommended in l	kitchen counter are	eas near the sink

Kitchen Appliances Job: xxxx Jean St

Built-in and Major Appliances

Appliance	Operation	nal	Condition	Comments
Refrigerator	N	res lo lot tested	Good x Fair Marginal Poor	Maytag. Unit was unplugged, after pluggin in, it appears to be cooling correctly
Freezer	x N	res lo lot tested	Good Fair Marginal Poor	t appears to be cooming correctly
Garbage disposal	x N	es lo lot tested	Good Fair Marginal Poor	
Dishwasher	N	es s lo lot tested	x Good Fair Marginal Poor	Maytag
Range (oven)	N	res lo lot tested	Good x Fair Marginal Poor	Magic chef, Left rear burner not functioning.
Microwave oven	x N	res lo lot tested	Good Fair Marginal Poor	
Cooktop	x N	es lo lot tested	Good Fair Marginal Poor	
Trash compactor	x N	es lo lot tested	Good Fair Marginal Poor	
Range hood	N	es 2 lo lot tested 2	x Good Fair Marginal Poor	Broan, recirculated vent
	N	res lo lot tested	Good Fair Marginal Poor	

copyright 2000-2002

Management Science Institute

all rights reserved

Appliances Job# xxxx Jean St

Built-in and Major Appliances

Appliance	Operat		Condition	Comments
Clothes washer	Х	Yes No Not tested	Good Fair Marginal Poor	
Clothes dryer	Х	Yes No Not tested	Good Fair Marginal Poor	
Water softener / filter	X	Yes No Not tested	Good Fair Marginal Poor	
Whole House fan	X	Yes No Not tested	Good Fair Marginal Poor	
Security system	X	Yes No Not tested	x Good Fair Marginal Poor	Unit has power and registers open windows and door. Not fully tested
		Yes No Not tested	Good Fair Marginal Poor	
		Yes No Not tested	Good Fair Marginal Poor	
		Yes No Not tested	Good Fair Marginal Poor	
		Yes No Not tested	Good Fair Marginal Poor	
		Yes No Not tested	Good Fair Marginal Poor	

Bathrooms Job: xxxx Jean St

Item / Attribute				cript num			Cor	nditi	on			
	1	2	3	4	5		1= 1	mas	ter, :	2=g	uest	t
Location		х				First floor			•			
						Second Floor	The	num	ber a	t the	top o	of each column refers to the bathroom
	Х					Master bedroom						
						See comments	num	ber.				
	1	2	3	4	5		1	2	3	4	5	
Electrical		T	Ī	<u> </u>	Ť	GFCI protected				-	Ť	Good
outlets	Х	х				Not GFCI*						Fair
	Х	х				See comments						Marginal
					•	_	X	х				Poor
	1	2	3	4	5		1	2	3	4	5	
Toilet	X	х				Std. gravity flush	X	Х				Good
						Pressure flush						Fair
						O.H. gravity flush						Marginal
						See comments						Poor
	1	2	3	4	5		1	2	3	4	5	
Plumbing	X					No leaks visible	Х					Good
		Х				Leaks visible		X				Fair
						Corrosion						Marginal
						See comments						Poor
	1	2	3	4	5		1	2	3	4	5	
Shower /	X	х				Shower						Good / Fair
tub	X	Х				Tub		х				Needs caulk or grout
						Spa						Leaks
						See comments	X	Х				Needs Repair

Additional comments

GFCI plugs in both bathrooms are not functioning as designed. Recommend replace GFCI plugs

Master bath-Large hole in wall next to toilet from missing paper holder. Recommend patch or replace with new.

Master bath-tub spout shower diverter knob is stuck and shower is always on. Recommend replace tub spout

Guest bath-tub faucet is leaking severely from handle when turned on. Recommend replace internal stem if available.

Note: RED check boxes, when checked, indicate that attention is needed. Failure to attend to these items may result in damage or create a sa hazard.

Plumbing Job: xxxx Jean St

General

Item /	7 1		Comments	
Attribute	Description			
Main shut-off valve(s)	X Supply side House side See comments	x Good / fair Leaks Corrosion Unable to cl	lose	
Piping	x No leaks visible Leaks visible Corrosion See comments	x Good Fair Marginal Poor	Copper and PVC	
Soil stack (vent), drain	х	x Good Fair Marginal Poor	PVC	
Sump pump	Yes No Backup system See comments	Tested Not tested No cover Broken		
Water Heater	X Electric Gas See comments	x Good / fair Leaks Corrosion Replace		
	x Pressure relief	Pressure re Safety hazard	elief missing / Incorrectly installed	
Age (app	orox.) <u>6-8 years</u>	Capacity	40 Gallons	

Additional Comments

1 dutional Comments
All sinks in house are plugged and filled with water. The water is left standing for duration of inspection and then sink is emptied and checked for leaks.
Washer connection valves are both actively leaking and have caused damage to surround wall
and baseboard. Recommend replace both valves and drywall to prevent mold.
Note: RED check boxes, when checked, indicate that attention is needed. Failure to attend to these items may result in damage or create a safety hazard.

Heating and Cooling

Job: xxxx Jean St

Primary Heat Source

Item /	Type /	Condition	Comments
Attribute	Description		
Heat source	x Forced air furnace Gravity furnace Electric baseboard Boiler Heat Pump (Electric)	x Good / fair Marginal Damage Needs Repair Unable to test	Electric heat strips / Missing pcs.
Brand name	Janitrol A/H, GrandAire condenser		Age: 12-15 years
Model	GS3BA-030KA		Capacity: 2.5 ton
Other			
Humidifier	Yes x No See comments	Good / fair Leaks Corrosion Poor	
Gas	Service piping	Good	Visual inspection. Gas lines are not pressure tested.
Line	See comments	Fair	
		Marginal Poor	
Flue piping	Plastic Galvanized steel mixed types See comments	Good Fair Marginal Poor	
Distribution	Sheet metal	x Good	
	x Flex duct	Fair	
	Zoned x Rigid fiberboard	Marginal Poor	

Primary Cooling System

Item / Attribute	Type / Description	Condition	Comments
Cooling source	x Whole House Forced Air Window Other See comments	x Good Fair Marginal Poor Unable to te	est
Distribution	Sheet Metal x Flex Duct Zoned x Rigid Fiberboard	x Good Fair Marginal Poor	Temp Differential: 21.6 F Excellent
Comments:			December of manifest due have been
•	ase snows signs of previous water dam missing filter. Recommend replace filt		up. Recommend monitor due heavy use.

Additional comments

Air Handler electrical disconnect is broken and bypassed. Recommend installing new disconnect.

Note: RED check boxes, when checked, indicate that attention is needed. Failure to attend to these items may result in damage or create a safety hazard.

Electrical System Job: xxxx Jean St

Service

Item / Attribute	Type / Description	Condition	Comments
Service location Brand name	Laundry ITE	x Good Fair	Copper wiring
Main disconnects (#) System voltage	1- 150A 120-240 VAC	Marginal Poor	
Main overcurrent device	Fuse x Breaker Mixed types See comments	x Good Fair Marginal Poor	
Ampere rating	200A meter socket		
Service entrance	x Overhead, cable Overhead, conduit Underground See comments	x Good Fair Marginal Poor	
Smoke	x Bedrooms/Vicinity	Good	All detectors are broken.
Detectors	x Kitchen Garage	Fair Loose x Broken	Recommend replace all detectors
Ground	x Water line x Ground rod See comments	x Good Fair Loose Needs repa	air
GFCI Breakers/ AFCI Breakers	Bath/Kitchen/Exterior Bedrooms	Tested Not tested	
Additional Com	monts		

Note: RED check boxes, when checked, indicate that attention is needed. Failure to attend to these items may result in damage or create a safety hazard.

Note: A representative number of devices were visually checked. Not all switches, light fixtures, outlets, and other devices were checked. Overcurrent devices were visually checked but NOT tested. GFCI outlets are recommended in all bathrooms, basements, workshops, pool areas, garages, and outdoors where there is grade level access.

Bedrooms Job: xxxx Jean St

Item / Attribute	Type / Description	Condition	Comments
Flooring	x Carpet Tile Wood See comments	x Good Minor cracks Uneven Damaged	
Walls	x Plaster/Drywall Masonry Wood See comments	x Good Minor cracks Damaged Unstable	
Doors	Wood Hollow Core See comments	x Good Fair Marginal Poor	
Closets	Hinged door x Bifold door Sliding door Storage components See comments	x Good Fair Marginal Poor	
Electrical	x 110 VAC x Switched light Switched Receptacle x Ceiling fan	Good / fair Sag/deflection Cracks X Needs repair	
	See comments See comments		
Additional Cor		alled properly. Recom	mend correct installation.

Trinity Contracting, LLC 321-591-7168 **Swimming Pool**

nming Pool		xxxx Jean St
ming root	Job #	XXXX JEan St

Ge	neral					
	Item		Comments			
	X	Fencing	6' wooden privacy fence			
	x	Latching gate	Rear of property is enclosed by a 6' wood	len picket f	ence. Both sides ha	ave a gate with appropriate latch
		Coping				
		Concrete				
	Х	Deck	Partial wooden deck around pool			
		Ladder				
		Slide				
		Diving board				
		Caulk				
		Water				
		Water valve				
		Sidewalk				
Add	itional c	comments:				
He	ater a	nd Electrical	Comments	Electric	al.	Comments
ı	neater	Natural gas	Comments	Electric	Wiring	Comments
		Electric			Underwater lights	
		Solar			Area lights	
		Solai		х	GFCI outlets	GFCI outlet for pump motor
		Shut-off valve			Non-GFCI outlets	
		Gas line				
		Burner(s)			Circ pump timer Jet pump timer	
		High temp switch Flow switch			Disconnect	
Add	itional c	comments:				
Wa		ilters and Pun				O community
	Filter X		Comments Filter is elegand	Pumps X	Circulation pump	Comments
	-^ -	Filter	Filter is clogged		Attachment	Pump leaks and will not turn on. Recommend replace pump
		Housing Fittings				
		•			Sweep pump Attachment	
		Pressure gauge Bleeder valve			Jet pump	
		Supply line			Attachment	
					Auxiliary pump	
		Discharge line Pressure switch			Water feature pump	
		Fressure Switch			water leature pump	
Δdd	itional c	comments:				
Auu	itionar	Jonnients.				
		C				
Add	ntional	Comments:				

Photographs



xxxx Jean St



5020 Jean St



Front door wood rot in jamb



Front door wood rot in jamb



Screen room kickplate loose



Pool pump leaking and not working



Crumpled fascia on East side



East side large settlement cracking



East side large settlement cracking



Chimney and cap needs painting



Garage GFCI malfunctioning



Texture missing in garage



Texture missing in garage

Photographs



xxxx Jean St



Washer valve actively leaking



Water damage to wall in laundry



Ceiling fan loose



French door slide lock missing



Air handler disconnect broken



Previous water damage on base



Air handler missing filter



Master faucet "stuck" on shower



Missing toilet paper holder



Hall bath faucet handle leaking



All smoke detectors are broken



Broken fireplace screen

Summary Job: xxxx Jean St

Items in RED are considered urgent items that need immediate attention
1. Panel is loose and bent on kickplate on rear porch next to screen door. Recommend reattach \$10
2. Chimney needs caulked and painted. Chimney cap loose and needs painted \$100
3. Gutters are full of debris and do not drain properly. Recommend clean out and seal joints and corners \$50
4. Stucco has large settlement crack on East side next to window. Recommend seal crack, stucco patch, and paint \$100
5. Front door has wood rot on lower 6 inches of both sides of door jamb. Recommend replace bottom of jambs \$100
6. Fascia on east side gable has large dent and fold. Not sure as to cause. Recommend remove and inspect for truss damage
7. Rear french door is missing bottom slide lock on stationary door, doors will not lock properly. Recommend replace lock. \$50
8. GFCI plug and circuit is not functioning as designed. Recommend replace GFCI plug \$50
9. Garage ceiling has several area of missing popcorn texture. No sign of water leak/damage. Common occurance due to humidity.
10. Fireplace screen is broken and off track. Recommend replace screen \$75
11. Left rear burner of stove is not working. Recommend replace element. \$50
12. Washer connection valves are both actively leaking and have caused damage to surround wall
and baseboard. Recommend replace both valves and drywall to prevent mold. \$200
13. GFCI plugs in both bathrooms are not functioning as designed. Recommend replace GFCI plugs \$100
14. Master bath-Large hole in wall next to toilet from missing paper holder. Recommend patch or replace with new. \$50
15. Master bath-tub spout shower diverter knob is stuck and shower is always on. Recommend replace tub spout \$50
16. Guest bath-tub faucet is leaking severely from handle when turned on. Recommend replace internal stem if available. \$100
17. Air handler base shows signs of previous water damage from water backup. Recommend monitor due heavy use.
18. Air handler is missing filter. Recommend replace filter \$15
19. Air Handler electrical disconnect is broken and bypassed. Recommend installing new disconnect. \$150
20. All detectors are broken. Recommend replace all detectors. \$75
21. Ceiling fan in purple bedroom is loose and not installed properly. Recommend correct installation. \$100
22. Pool pump leaks and will not turn on. Recommend replace pump \$300-400